

FIRING SCHEDULES

Conor's Cone 6:

Rate (Ra)	Temp (F)	Hold (HLD)
225	2200	0.00
9999	2050	0.30

Conor's Cone 6 Slow Cool:

Rate (Ra)	Temp (F)	Hold (HLD)
350	2050	0.00
120	2200	0.00
9999	1950	0.00
200	1500	0.00

Camille Hoffman Schedule (Perry – Skutt):

Rate (Ra)	Temp (F)	Hold (HLD)
200	250	0.00
400	1000	0.00
180	1150	0.00
300	1967	0.00
120	2180	0.05
125	1900	0.30

C4 Crystalline Schedule Cone 7:


Rate (Ra)	Temp (F)	Hold (HLD)
250	250	0.10
500	1978	0.00
150	2250	0.15
500	1875	0.45
500	1810	0.15
250	1875	0.45
500	1810	0.10
250	1900	0.45

Ask Conor for Simair Base Glaze Recipe if interested


CONTROLLERS



Skutt KilnMaster Touchscreen



Skutt KilnMaster (keypad)



Orton Sentry 2.0